

WOS

PUSH-PULL EXR

PVS (Peripheral Vision System)

This enables real-time visual checking of the correct functioning of the motor.

More thrust and less wire deformation thanks to its extremely precise orbital system. The upper casing can be removed manually for roller adjustment and wire replacement.

Connections are protected from the line of movement of the arm as it interacts with the welding peripherals.

Completely modular system with easily removed parts for repair or replacement and compatible with all models from the EXR range.



This is a revolutionary system which relates torch temperature and the current parameters, warning you of any abnormal damage to any of its electric parts, allowing for you repair or change once work is finished thereby avoiding unwanted interruption of its normal function.